



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representativ	ves Present During the Inspection:	
OGM	Priscilla Burton	

Inspection Report

Permit Number:	C0070001
Inspection Type:	PARTIAL
Inspection Date:	Monday, February 28, 2011
Start Date/Time:	2/28/2011 2:30:00 PM
End Date/Time:	2/28/2011 3:30:00 PM
Last Inspection:	Monday, January 03, 2011

Inspector: Priscilla Burton,

Weather: sun 30 F

InspectionID Report Number: 2663

Types of Operations

Accepted by: jhelfric

3/3/2011

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director Permitee: LODESTAR ENERGY INC

Operator:

Site: WHITE OAK MINE

Address: ,

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current	Anronnos
Current	Acreages

3,906.00	Total Permitted
151.10	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

	•		
✓ Fede	ral	✓	Underground
✓ State		✓	Surface
✓ Coun	ity	\checkmark	Loadout
✓ Fee			Processing
Other	•		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The loadout and mine site are snow covered. Mine site is inaccessible.

Inspector's Signature

Inspector ID Number: 37

Priscilla Burton,

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov

Utah!

Date

Monday, February 28, 2011

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Monday, February 28, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations		Ameri		
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		~	
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	V		Y	
16.1	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070001 Inspection Type: PARTIAL

Inspection Date: Monday, February 28, 2011

Page 3 of 3

9. Protection of Fish, Wildlife and Related Environmental Issues

Snow drifts adjacent to the river prevented me from getting a look at the confluence of Whiskey Creek and Eccles Creek.

16.a Roads: Construction, Maintenance, Surfacing

Gates to both the loadout and mine site were open. A single lane access to the loadout had been plowed. The logger's equipment was parked at the mine site access road gate and at the first bend in the road. The mine site access road had been plowed (at least to the bend) before last week's storm. The site was inaccessible.